


Tree Impacts and Arborist Assessment

- Construction Impact Removal (Total 6)
- Poor Suitability for Preservation (Total 52)*

* On October 1, 2012, two trees (# 41 & 42) slated for removal have been damaged by natural causes whereby their entire canopy snapped off and fell into the pathway above playground leaving only tall snags.

Note: Trees rated with poor suitability are in poor health and have significant defects in structure that cannot be addressed through pruning or other measures.

- Proposed New Trees (163)
 - Existing Trees to Remain
- #1-442 Tree Tag Number




Updated 10.3.2012

Xrefs: V:\3071V Glen Canyon Park\2_Design\Working_Drawings\EIA\BOE9_TBE.dwg
 V:\3071V Glen Canyon Park\2_Design\Working_Drawings\EIA\BOE9_Plans\010-40 Glen Canyon Park (completion).dwg
 V:\3071V Glen Canyon Park\2_Design\Working_Drawings\EIA\BOE9_Plans\3071V_LL_EXST.dwg
 Drawing Path: V:\3071V Glen Canyon Park\2_Design\Working_Drawings\EIA\3071V_LL-10-14_DEMO.dwg. Logfile: 10/1/2012 10:10:10 AM. Scale: 10
 Plot Time: Wed, 22 Aug 2012 11:33:58 AM. Measurement Units are English

1	NOV 2012	REVISION DUE TO TREE COUNT ERROR		
TABLE OF REVISIONS				
NO.	DATE	DESCRIPTION	BY	APP.
THIS DRAWING WAS LAST MODIFIED: 06/13/12 14:19, BY: ebliss				

REFERENCE INFORMATION
& FILE NO. OF SURVEYS



INFRASTRUCTURE DIVISION
 DEPARTMENT OF PUBLIC WORKS
 CITY AND COUNTY OF SAN FRANCISCO



DESIGNED: DATE:	APPROVED:
KP/KO/JPS/12	
DRAWN: DATE:	SECTION MANAGER:
EB 05/12	
CHECKED: DATE:	DEPUTY DIVISION MANAGER:
	DIVISION MANAGER:

SCALE:
1"=30'-0"
SHEET OF SHEETS
OF

GLEN CANYON PARK IMPROVEMENTS
TREE PLANTING AND REMOVAL PLAN

CONTRACT NO.	3071V
DRAWING NO.	
FILE NO.	
REV. NO.	