

Task Force Members:

At our first meeting, some questions arose regarding the 9 playground sites where the grades had improved in the 2014 Reassessment (published by SF Parks Alliance).

In response to requests from Failing Playground Task Force Members, attached is a summary of the work orders completed by the Recreation and Parks Department at these 9 playground sites. The work order list is being provided so each Task Force Member can assess for him/herself if the amount of work completed is substantial enough to account for the improvement in grade. If you feel the work completed is not substantial enough to account for the improvement in the grade, it may be that human error on the part of one or both of the surveyors are responsible. For example, it could be that one or both of the surveyors missed seeing and recording some negative elements of the site, resulting in a more positive grade.



Failing Playgrounds Task Force

sfrecpark.org/failing-playgrounds-2012-bond

In partnership with



<u>Playground</u>	<u>Type of Work Order</u>	
Alioto Mini Park	Install/Replace Sign	1
	Paint play structure	1
	Repair/Replace play matting	1
	Repair/Replace Other Play Apparatus	1
	Paint Signage	1
	Repair/Replace Water Fountain	2
	Paint Graffiti	1
	Repair/Replace Lock / Latch	1
	Total # of Work Orders	9
Bernal Heights Recreation Center	Install/Replace Sign	1
	Repair cargo container	2
	Paint Graffiti	6
	Repair/Replace play matting	1
	Repair/Replace Swing Seat	2
	OE General Maintenance	2
	Repair/Replace Cement	1
	Repair/Replace Other Play Apparatus	3
	Total # of Work Orders	18
Golden Gate Heights Park	Repair/Replace Plumber/Steamfitter work	1
	Welding	1
	Repair Gate	1
	Repair/Replace Water Fountain	1
	Repair water leak	1
	Repair/Replace Chain	1
	Total # of Work Orders	6
Miraloma Playground	IW-015 - Repair Gate	1
	PL-018 - Repair water leak	1
	PL-035 - Repair/Replace Water Fountain	1
	Total # of Work Orders	3
Palou-Phelps Park	Paint Graffiti	4
	Repair/Replace play matting	1
	Repair/Replace Basketball hoop	1
	Repair/Replace Other Play Apparatus	2
	Total # of Work Order	8

(Over)

Precita Park	Repair Gate	1
	Paint Graffiti	8
	Repair/Replace Other Play Apparatus	3
	Repair/Replace Swing Seat	3
	Repair/Replace Swing Parts	3
	Repair/Replace/Construct Tables	1
	OE General Maintenance	3
	Paint Exterior (Merry go round)	1
	Total # of Work Orders	23
Macaulay	Repair/Replace Other Play Apparatus	3
	Repair/Replace Swing Parts	1
	Repair/Replace Swing Seat	1
	Total # of Work Orders	5
Silver Terrace	Paint Graffiti	4
	Repair/Replace Other Spots Apparatus	1
	OE General Maintenance	1
	Repair/Replace broken Swing	1
	General (carpentry)	1
	Repair/Replace clamps	1
	Total # of Work Orders	9
States Street	Drive Vactor Truck	1
	Paint Grafitti	8
	Operate Loader	1
	Operate Bucket Loader	1
	Total # of Work Orders	11

Closed Work Orders 7/01/2012 through 12/31/2013

WO #	Requested	Task Closed	Property	Functional Area	Task Code-Description	Type-Description	Request
SM-098815	6/19/2012	9/13/2012	Alioto Mini Park	Alioto: CPA	IW-011 - Install/Replace Sign	Iron Work	Please install "NO ADULTS UNLESS WITH CHILD" somewhere near Play Area.
SM-099960	7/13/2012	8/22/2012	Alioto Mini Park	Alioto: CPA	PA1016 - Paint play structure	Painting	Re. 4th quater eval. Worn or chipped paint on playground equipment. Please assess/re-paint.
SM-099963	7/13/2012	9/16/2013	Alioto Mini Park	Alioto: CPA	CE1025 - Repair/Replace play matting	Cement Masonry	Re. 4th quater eval. Please assess/replace safety surface due to possible tripping hazards etc.
SM-102788	9/12/2012	9/13/2012	Alioto Mini Park	Alioto: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	311 Request 1411699 -- 20th St / Capp St - in the Children's Playground next to the monkey bars --- The parallel bar used to do pull ups or for the kids to hang off of, is extremeley loose. It needs to be tightened.
SM-102889	9/13/2012	9/13/2012	Alioto Mini Park	Alioto: CPA	PA-010 - Paint Signage	Painting	Please make sign "NO ADULTS WITHOUT CHILDREN"
SM-103508	9/28/2012	10/3/2012	Alioto Mini Park	Alioto: CPA	PL-035 - Repair/Replace Water Fountain	Plumbing	Drinking fountain is clogged please repair.
SM-109379	2/12/2013	2/26/2013	Alioto Mini Park	Alioto: CPA	IW-028 - Repair/Replace Lock / Latch	Iron Work	Latch is missing or broken from the gate to the play area, please repair.
SMY-111205	3/22/2013	3/26/2013	Alioto Mini Park	Alioto: CPA	PA-008 - Paint Graffiti	Painting	Graffiti on play equipment at Alioto park, thanks
SMY-116001	6/20/2013	6/25/2013	Alioto Mini Park	Alioto: CPA	PL-035 - Repair/Replace Water Fountain	Plumbing	Drinking fountain is blocked, please repair, thanks
SM-089719	11/30/2011	9/19/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-011 - Install/Replace Sign	Iron Work	Please install two no smoking signs in the children's play area.Please use your descretion on placement in the playground.We have had request from the public that these signs be installed.
SM-095534	4/16/2012	11/28/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-014 - Repair cargo container	Iron Work	We have a green wooden storage box in the children's play area near the tire swing that needs the top repaired. There is a hole in the top of the box that needs to be sealed.
SM-096380	5/3/2012	11/28/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-014 - Repair cargo container	Iron Work	We recently requested a repair to the top of the green storage box in the children's play area. The repair is now failed and another repair is needed.
SM-099830	7/11/2012	7/12/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	Graffiti on retaining walls of tree planter in the middle of the play area.
SM-099884	7/11/2012	10/15/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	CE1025 - Repair/Replace play matting	Cement Masonry	Please repair hole in the safety surface in the childrens play area. It's near the front entrance.
SM-101608	8/16/2012	8/20/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	We have black graffiti on the top of the retaining wall /flower bed located at the back of the library that is part of the RPD children's playground.The location is at the ramp that goes down to the back door of the library.
SM-103043	9/17/2012	9/25/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	We have an S hook that has come loose on the tire swing play equipment at Bernal Playground.We would like the tire swing repaired please. Also replace worn S hooks on the rings.
SM-106288	11/29/2012	11/28/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-999 - OE General Maintenance	Iron Work	One of the swings has a piece of metal sticking out. The gentlemen from the yard was here working on something else and was kind enough to file it down. It needs to be replaced. It is the fourth swing from the big tree. I think.
SM-106352	11/30/2012	11/30/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-999 - OE General Maintenance	Iron Work	Replace broken baby swing seat.
SM-106508	12/3/2012	12/10/2012	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-033 - Repair/Replace Swing Seat	Iron Work	Toddler swing seat has sharp edges. Needs to replace
SM-110051	2/28/2013	6/25/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	Please remove the recntly vandalized/burned tunnel slide unit. We are unable to prevent children from accessing and using this damaged and broken unit while it is awaiting replacement.
SMY-116743	7/3/2013	7/8/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-032 - Repair/Replace swing parts	Iron Work	We have a toddler swing at Bernal recreation that a teenager became stuck in and the fire department had to cut the swing off. The swing is removed from the site and we need a replacement swing installed please. I am not aware of the location of the swing seat that was removed by the fire department.
SMY-117969	7/29/2013	7/31/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	311 request 2648251 -- On the City Can that's built into the stone wall of the park entrance at Bernal Heights Blvd/@Anderson. --- Graffiti on the built in City Can.
SMY-118271	8/5/2013	8/8/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-032 - Repair/Replace swing parts	Iron Work	311 request 2676083 -- The swing in the middle section, in the playground. --- The top part of the middle swing is coming loose and needs to be screwed in tight.

SMY-120158	9/16/2013	9/17/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	311 request 2818710 -- Bernal Height Blvd and Anderson couth entrance behind the locked gates --- on bench 3, 4, and 6 311 request 2910198 -- on the Ripley side of park --- wooden Bench overlooking city - Graffiti
SMY-121073	10/7/2013	10/8/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	Please let Joe know when completed. 311 request 2909626 -- Bench in Bernal Heights park. From the entrance at Folsom St it's aprox a couple hundred feet up park road. --- Graffiti located on Bench in Bernal Heights park. From the entrance at Folsom St it's aprox a couple hundred feet up park road. pic.twitter.com/wadodBovjY
SMY-121076	10/7/2013	10/8/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	PA-008 - Paint Graffiti	Painting	In the upper playground we have a long concrete bench along the back of the library that has two exposed rebars that should be removed.The exposed rebars are at the east end of the bench on the lower side. We got a 311 on this from a parent that claimed the rebars could be dangerous to children.
SMY-121459	10/15/2013	11/22/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	
SMY-121599	10/17/2013	10/18/2013	Bernal Heights Recreation Center	Bernal Heights: CPA	CE-014 - Repair/Replace	Cement Masonry	Two rusty peaces of metal are sticking uot of large concrete bench at Bernal heighths p/g
SM-099714	7/9/2012	12/14/2012	Golden Gate Heights Park	GG Heights: CPA	PL-031 - Repair/Replace Plumber/Steamfitter work	Plumbing	Drink fountain near cpa. please extend slot drain to line two sides of cement platform and reduce puddling around fountain.
SMY-113365	5/2/2013	5/21/2013	Golden Gate Heights Park	GG Heights: CPA	IW-025 - Repair/Replace	Iron Work	311 request 2313443 -- Chain that connects picnic table at that children't playground is being reported as broken. iron shop...vandal has removed bench from its usual spot and chained it up inside of CPA. please cut chain so we can retrieve bench. Also, please weld lock and chain to CPA gate.
SMY-120664	9/26/2013	10/7/2013	Golden Gate Heights Park	GG Heights: CPA	IW-043 - Welding	Iron Work	~ Pls. replace latch on the gate at the top of the staircase leading down to the ballfield.
SM-106130	11/27/2012	12/12/2012	Miraloma Playground	Miraloma: Park - CPA	IW-015 - Repair Gate PL-018 - Repair water leak	Iron Work Plumbing	Water leak next to slide. Dug down 2.5 feet did not find pipe. Also leak on field--could be related.
SMY-112750	4/19/2013	4/23/2013	Miraloma Playground	Miraloma: Park - CPA	PL-035 - Repair/Replace Water Fountain	Plumbing	water fountain is clogged, unusable
SMY-117754	7/23/2013	8/1/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	CE-018 - Repair/Replace PIP Play Matting	Cement Masonry	The rubber matting in the CPA has holes and is need of repair at Palou/Phelps Mini Park.
SMY-117760	7/23/2013	7/24/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	PA-008 - Paint Graffiti	Painting	There is graffiti on the retaining wall behind the CPA at Palou/Phelps Mini Park.
SMY-117813	7/24/2013	7/25/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	PA-008 - Paint Graffiti	Painting	311 request 2634447 -- Playground at the intersection of Palou Ave and Phelps St --- Children's playground is covered in graffiti tags on ground and play structure.
SMY-117817	7/24/2013	10/1/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	IW-026 - Repair/Replace Basketball Parts	Iron Work	311 request 2634440 -- Basketball court at the intersection of Palou Ave and Phelps. --- Basketball hoop is broken off and attached to a nearby tree.
SMY-118569	8/12/2013	8/15/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	PA-008 - Paint Graffiti	Painting	Graffiti on play structure and bench by basketball courts.
SMY-118720	8/15/2013	10/11/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	311 request 2705750 -- Rocking dolphin ride-on is broken--needs to be secured to spring.
SMY-120010	9/11/2013	10/11/2013	Palou-Phelps Park	Palou: CPA - east school age area (2)	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	There is a piece of play equipment missing , I believe it to be a hobbie horse in the CPA at Palou/Phelps Mini Park.
SMY-120580	9/24/2013	9/25/2013	Palou-Phelps Park	Palou: CPA - west tots area (1)	PA-008 - Paint Graffiti	Painting	311 request 2866044 -- Play structure - Palou & Phelps Mini Park --- Graffiti on children's play structure at palou-phelps mini park
SM-085589	8/26/2011	12/17/2012	Precita Park	Precita: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	We have four clamps that are cracked on the children's play structure. The clamps are located at the top of the play structure and I have caution taped them . Please remove two links from the older childrens swing licated two over from the west. The swing is now too close to the new surface. We had a walk through with capitol today and they requested that I place this TMA into the system to bring the swing into the 14" zone abover the new rubber matting.
SM-099472	7/2/2012	9/14/2012	Precita Park	Precita: CPA	IW-032 - Repair/Replace swing parts	Iron Work	I have a gate that opens wide enough for a vehicle entering the children's play area at Alabama and South Precita. This gate is out of allingement and the parents will have a hard time closing it.
SM-099474	7/2/2012	8/22/2012	Precita Park	Precita: CPA	IW-015 - Repair Gate	Iron Work	Vandalism: Carpenters needed to replace 4 planks on picnic table in the childrens play area. The Planks are fire damaged due to fireworks from the 4th of July.
SM-099596	7/5/2012	8/6/2012	Precita Park	Precita: CPA	CA-016 - Repair/Replace/Construc t - Benches or Tables	Carpentry	priority: High

SM-100331	7/16/2012	8/31/2012	Precita Park	Precita: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	We have a spinning metal toy that looks like a fling saucer. The hand grasp welds are coming loose and we would like to have them rewelded.
SM-101365	8/10/2012	8/13/2012	Precita Park	Precita: CPA	PA-008 - Paint Graffiti	Painting	graffiti on retaining wall by the picnic tables. priority: High
SM-101550	8/15/2012	9/14/2012	Precita Park	Precita: CPA	IW-999 - OE General Maintenance	Iron Work	The tire swin at Precita has an S hook that is detached and in need of repair. I have placed danger tape on the structure to close it down and keep the moms from rehooking the S hook up and then letting the kids play on something that could slip off at anytime.
SM-101609	8/16/2012	9/14/2012	Precita Park	Precita: CPA	IW-033 - Repair/Replace Swing Seat	Iron Work	The tire swing inthe children's playground has a detached "S" hook and needs repair. I have placed danger tape on the tire swing to keep the youth off. priority: High
SM-102640	9/10/2012	9/11/2012	Precita Park	Precita: CPA	IW-999 - OE General Maintenance	Iron Work	We have a swing seat that is broken through and needs replacement. I got a complaint about the swing seat and the missing tire swing. I have explained that the tire swing is in the process of being repaired. priority: High
SM-103831	10/5/2012	10/5/2012	Precita Park	Precita: CPA	IW-033 - Repair/Replace Swing Seat	Iron Work	The tire swing at Precita has a broken chain.We have placed caution tape on the swing .
SM-106167	11/27/2012	11/30/2012	Precita Park	Precita: CPA	PA-008 - Paint Graffiti	Painting	Web have graffiti on the play equipment in Precita Park. The graffiti is located on a lavender cross pipe on the west side of the playground just off the concrete walk near the west side pedestrian gates.
SM-107515	12/31/2012	1/2/2013	Precita Park	Precita: CPA	PA-008 - Paint Graffiti	Painting	Graffiti on top of the slide at Precita Park playground, thanks priority: High
SM-108373	1/18/2013	1/22/2013	Precita Park	Precita: CPA	PA-008 - Paint Graffiti	Painting	We have graffiti on the plastic bubble part of the main play structure.
SM-110521	3/11/2013	3/12/2013	Precita Park	Precita: CPA	IW-033 - Repair/Replace Swing Seat	Iron Work	311 request 2109246; Precita Park playground near 417 Precita --- Twitter resident states: Broken swing at Precita Park playground (near 417 Precita): See photo: pic.twitter.com/JcR5yXOQ9H Please let Joe know when completed.
SMY-114010	5/15/2013	5/21/2013	Precita Park	Precita: CPA	IW-032 - Repair/Replace swing parts	Iron Work	Two Toddler's Swing are disconnected from the S-Link. The swing seats are hanging and we have caution taped it. graffiti on large picnic table in playground area and
SMY-114526	5/28/2013	5/29/2013	Precita Park	Precita: CPA	PA-008 - Paint Graffiti	Painting	on new signs bordering on Harrison St. --- black tagging on the back of the north sign, silver tagging on the front of the south sign
SMY-114569	5/28/2013	10/1/2013	Precita Park	Precita: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	The merry go round is turning slowly and may need grease or adjustment to turn faster. I am reporting this after a member of the public made a complaint.
SMY-120516	9/23/2013	10/30/2013	Precita Park	Precita: CPA	TD-008 - Drive Crane Truck	Transporting	Please deliver merry go round to Precita Park. One of the swings are broken need to be repair Thanks ~LOCATION DETAILS~ Precita Park Precita Park Play Structures Precita: CPA ~~~~~
SMY-123423	12/2/2013	12/6/2013	Precita Park	Precita: CPA	IW-032 - Repair/Replace swing parts	Iron Work	
SM-101842	8/22/2012	8/22/2012	Precita Park	Precita: CPA 2	EL-999 - EL General Maintenance	Electrical	Please bend handle for Merry Go Round. Chris will give instructions on work needed to be done.
SM-109898	2/26/2013	2/27/2013	Precita Park	Precita: CPA 2	PA-008 - Paint Graffiti	Painting	Graffiti on the bubble of the play structure Note from Joe: This is an old request, it may have been completed through a different TMA.
SMY-115409	5/23/2013	6/13/2013	Precita Park	Precita: CPA 2	PA-008 - Paint Graffiti TD-008 - Drive Crane	Painting	Wood picnic table in children playground has graffiti priority: High
SMY-120079	9/13/2013	10/30/2013	Precita Park	Precita: CPA 2	Truck PA-013 - Prep/Paint	Transporting	Winch truck needed to assist ironworkers on removal of Merry-Go-Round.
SMY-120192	9/16/2013	9/19/2013	Precita Park	Precita: CPA 2	Exterior	Painting	Please paint merry go round and deliver to iron shop when finished.
SMY-120370	9/19/2013	9/20/2013	Precita Park	Precita: CPA 2	PA-008 - Paint Graffiti	Painting	Graffiti on pathway near picnic area Needs to be removed

SM-102264	8/31/2012	9/17/2012	Sgt. John Macaulay Park	Macaulay: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	The rope swing in the children's play area is broken and creating a hazard.
SM-102999	9/14/2012	9/17/2012	Sgt. John Macaulay Park	Macaulay: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	Safety hazard Pls fix the broken bridge
SM-105704	11/16/2012	12/7/2012	Sgt. John Macaulay Park	Macaulay: CPA	IW-033 - Repair/Replace Swing Seat	Iron Work	311 request 1687711 -- Associated to Unverified address - Intersection of and ofarrell and larkin San Francisco, CA --- Sergeant John Macaulay mini park at O'farrell and Larkin streets. --- the hinge for the tire swing is about to break. the pin holding it in place is rusted through and the bar is almost completely out. entire swing likely to fall soon.
SM-108523	1/23/2013	1/28/2013	Sgt. John Macaulay Park	Macaulay: CPA	IW-030 - Repair/Replace Other Play Apparatus	Iron Work	Safety Hazard: Pls fix a broken bridge
SMY-113292	4/30/2013	5/2/2013	Sgt. John Macaulay Park	Macaulay: CPA	IW-032 - Repair/Replace swing parts	Iron Work	Safety hazard -- Pls fix the Broken tire swing. One of the screw is coming out
SM-087993	10/18/2011	7/2/2012	Silver Terrace Playground	Silver: CPA	swing parts PA-021 - Supervise	Iron Work	to chaotic swings when they're swung high. I think the rust has caused some metal to get worn away and thus allow the
SM-100099	7/17/2012	7/17/2012	Silver Terrace Playground	Silver: CPA	Volunteer Program	Painting	Painting of wood play structure with volunteers at play area.
SM-100113	7/18/2012	8/17/2012	Silver Terrace Playground	Silver: CPA	Maintenance	Carpentry	Please inspect and repair support posts of wood play structure (ROTTEN) .
SM-101555	8/15/2012	8/16/2012	Silver Terrace Playground	Silver: CPA	IW-999 - OE General Maintenance	Iron Work	fabricate metal brackets for play structure
SM-106453	12/3/2012	12/5/2012	Silver Terrace Playground	Silver: CPA	PA-008 - Paint Graffiti	Painting	311 request 1750179 -- External wall of park on the Silver Ave side --- Gang related graffiti, recently painted over has been re-tagged.
SMY-110973	3/18/2013	3/21/2013	Silver Terrace Playground	Silver: CPA	PA-008 - Paint Graffiti	Painting	311 request 2131856 -- Primary baseball field --- White tag graffiti on garbage can, back of fence, back of wall (next to main baseball field) and on building next to small managers building inside park.
SMY-114043	5/15/2013	5/21/2013	Silver Terrace Playground	Silver: CPA	IW-031 - Repair/Replace Other Sport Apparatus	Iron Work	311 request 2365626 -- playground where the swings are --- One of the infant swings (the seat area) is broken.
SMY-119708	9/5/2013	9/6/2013	Silver Terrace Playground	Silver: CPA	PA-008 - Paint Graffiti	Painting	There is graffiti on the benches in the CPA and on the service road at Silver Terrace Pg.
SMY-121429	10/15/2013	10/17/2013	Silver Terrace Playground	Silver: CPA	PA-008 - Paint Graffiti	Painting	311 request 2944614 -- AT SILVER TERRACE PARK ON THE BLEACHERS, SIDE WALL AND RESTROOM. --- GRAFFITI ON THE ABOVE LISTED LOCATIONS IN THE PARK.
SM-106776	12/10/2012	12/11/2012	States Street Playground	States Street: CPA	TD-006 - Drive Vactor Truck	Transporting	entrance to field is totally SWAMPED large pool of sitting water need vector truck asap
SMY-113706	5/8/2013	5/9/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti on play structures and park signs
SMY-113946	5/14/2013	5/16/2013	States Street Playground	States Street: CPA	OE-007 - Operate Loader	HEO	need heavy equipment to assist loading 50 cu's of sand into play ground TUESDAY 5/21
SMY-114573	5/28/2013	5/29/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti TD-009 - Operate Bucket	Painting	grafitti on slide
SMY-114858	5/31/2013	6/12/2013	States Street Playground	States Street: CPA	Loader	Transporting	Please provide a bucket loader to spread new sand at States Street Playground on Thursday June 6th.
SMY-115940	6/18/2013	6/20/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti on slide
SMY-115948	6/19/2013	6/20/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti
SMY-117185	7/11/2013	7/12/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	Graffiti on the bench in the CPA
SMY-123393	12/2/2013	12/3/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti on slide
SMY-123778	12/10/2013	12/12/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti on slide
SMY-124050	12/17/2013	12/18/2013	States Street Playground	States Street: CPA	PA-008 - Paint Graffiti	Painting	grafitti on slide